




Odin/ Bolt Laser head assembly diagram




M3x4 Phillips Head Screw: to secure lens mount to the cover plate.

M3x5 Thumb Screw: to secure cover plate to the laser head.




1.5-inch laser head assembly diagram:



2.0-inch laser head assembly diagram:



2.5-inch laser head assembly diagram:



4.0-inch laser head assembly diagram:

